











Date: Thursday, 26/07/2007 1:24:53 PM
User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: BLUE
Job Number	: 33747		
Estimate Number	: 10804		
P.O. Number	: <i>N/A</i>	Part Number	: D29322
This Issue	: 26/07/2007 S.O. No. : <i>N/A</i>	Drawing Number	: D29322
Prsht Rev.	: NC	Project Number	: <i>N/A</i>
First Issue	: <i>N/A</i> Type : SMALL /MED FAB	Drawing Revision	: <i>N/A</i>
Previous Run	: 33742	Material	: <i>N/A</i>
Written By	: <i>[Signature]</i>	Due Date	: 02/08/2007
Checked & Approved By	: <i>[Signature]</i>	Qty:	4 Um: Each
Comment	: <i>[Signature]</i>		

Seq. #:	Machine Or Operation:	Description :
1.0	PACKAGING 1	PACKAGING RESOURCE #1
		
	Comment: PACKAGING RESOURCE #1 PULL FROM STK: 4 X D2933-1UP B <i>32378</i>	
2.0	D29322UP	206 Saddle Right side-unpainted
		
	Comment: Qty.: 1.0000 Each(s)/Unit Total : 4.0000 Each(s) Lug Assembly-unpainted	
3.0	PG	PURCHASING
		
	Comment: PURCHASING PURCHASING ISSUE P.O. <i>4273</i> ATELIER DEBOSSSELAGE SPRAY PAINT DELFLEET BLUE CLEAR DELFLEET <i>u 27-07-27 4</i>	
4.0	PACKAGING 1	PACKAGING RESOURCE #1
		
	Comment: PACKAGING RESOURCE #1 RECEIVE AND INSPECT FOR TRANSIT DAMAGE <i>27/07/30 (u)</i>	
5.0	QC14	INSPECT SPRAY PAINT
		
	Comment: INSPECT SPRAY PAINT <i>27-07-30 (u)</i>	

Date: Thursday, 26/07/2007 1:24:53 PM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: BLUE

Job Number: 33747

Part Number: D29322

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1
ID & STK USING NEW B/N

7/7/30

4x

SD

7.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

20107131

Job Completion



2 7/7/30